


FIG.1



* SEND R99 PACKET MEASUREMENT REPORT MESSAGE

** SEND R97 PACKET MEASUREMENT REPORT MESSAGE

*** SEND R99 PACKET MEASUREMENT REPORT MESSAGE WITH NEW FIELD

'NC MEAS LIST TYPE'

FIG.2